



1983-B Grand Caillou Road  
751 Peters Road

Houma, LA 70363-7086  
Harvey, La. 70058

Tel: 985.580.9978

Fax: 985.580.9982

Tel 504-355-4-56 fax 504-366-2038

**Date: 6/25/24**

**Labmar Ferry Services**

M/V Thomas Jefferson  
Engine overhauls

To Whom It May Concern,

Force Power Systems has been servicing the M/V Thomas Jefferson for the past two years. Based on manufactures recommendations, both main engines, both generators engines, and the bow thruster engine are due for in-frame overhauls according to the service hours on each. It is Force Power Systems recommendation that these overhauls be performed while the ferry is in the ship yard to limit any further down time.

Each engine over haul would consist of replacing all cylinder kits, main and rod bearings, cylinder heads, turbochargers, and any other wear parts with new parts to insure optimal performance once the ferry is back in service.

Glen Cronian  
Service Manager  
[Glen.cronian@forcepowersystems.com](mailto:Glen.cronian@forcepowersystems.com)