

### Regional Transit Authority Solicitation Request Routing Sheet

INSTRUCTION: The user department is responsible for providing all information requested below and securing the requisite signatures.

## Attachments

(\*Indicates Required Items)

Scope of Work
 Technical Specifications
 DBE/SBE Goal Calculation

Project Schedule/Delivery Date \*
Selection Criteria (RFQ/RFP Only)

A. I have reviewed this form and the attachments provided and by signing below I give authority to the below stated Department Representative to proceed as lead in the procurement process.

Raymundo Delgadillo

Director of Bus Maintenanace

8359

Name

Title

Ext.

B. Name of Project, Service or Product:

Out of Shop Repairs

C. Justification of Procurement:

Our Bus Maintenance Department currently has multiple open vacancies, along with 5 mehcanis out on Short Term Disability or Workers Compensation. This reduction in labor has made it difficult to keep up with our aging fleet, and while we are getting newer buses, large majority of our fleet is still form 2008, or 2010.

Many of our Technicians have recently retired, it has become necessary to reach out for assistance from Authorized dealers to assist with diagnostics and advanced bus repairs.

D. Certification of Authorized Grant:

Is this item/specification consistent with the Authorized Grant?

Director of Grants/ Federal Compliance

Date

No

E. Safety: Include Standard Safety Provisions Only

Additional Safety Requirements Attached

Safety Director

8/1

Risk Management:

Include Standard Insurance Provisions Only?

Include Additional Insurance Requirements Attached

No



Risk Management Analy

8/2	4/2021
-----	--------

Date

F. Funding Source: Federal State	local Other:
Funds are specifically allocated in the Department's cur	rent fiscal year budget or in a grant to cover this
expenditure as follows:	
•	
Total Available Funding:	\$
Estimated Cost:	\$ \$150,000
	φ
FTA Grant No.(s)	
Line Item(s)	7
Operations/Department Code	
Budget/Code(s)	1430002.7360.06101
Il amost Ly hard	8/20/2021
Budget Analyst	Date / /
G. DBE BE Goal: 7 / W DBE	6 % Small Business
G. DBERGE GOIL.	8/19/202/
Director of Small Business Development	Date //
Director of Small business development	0/19/2/2/
14 N 06.	0/14/2001
DBE EEO Compliance Manager	Date
H. Authorizations: I have reviewed and approved the final sol	icitation document.
Family Delasello	8-19-2021
Department Head	Date
M. SAL	8/24/2121
Division Manager	Date
Start h. Balala	8/24/21
Director of Procurement	Date
	/ /
FOR PROCUREMENT USE ONLY	DEC DED GG TRUG GTED
Type of Procurement Requested: (circle one) <b>IFB</b> Invitation for Bid (IFB) This competitive method of awarding	RFQ RFP SS TWO-STEP
	which it made in the contract of well of when and how

in value. The agency knows exactly what and how many of everything it needs in the contract, as well as when and how the products and services are to be delivered. The award is generally based on price.

Request for Quote (RFQ) This type of solicitation is often used to determine current market pricing.

Request for Proposal (RFP)This approach to contracting occurs when the agency isn't certain about what it wants and is looking to you to develop a solution and cost estimate.

Sole Source (SS) this procurement can be defined as any contract entered into without a competitive process, based on a justification that only one known source exists or that only one single supplier can fulfill the requirements.

Two-step Procurment - request for qualifications step-one used in the formal process of procuring a product or service, It is typically used as a screening step to establish a pool of vendors that are then qualified, and thus eligible to submit



responses to a request for price proposal (RFP). In this two-step process, the response to the RFQ will describe the company or individual's general qualifications to perform a service or supply a product, and RFP will describe specific details or price proposals.

Date 9/21/2, Date

### Independent Cost Estimate (ICE)

#### INDEPENDENT COST ESTIMATE SUMMARY FORM

Project Name/Number:
Date of Estimate:
Description of Goods/Services:
Out of Shop Repairs
X New Procurement Contract Modification (Change Order) Exercise of Option
Method of Obtaining Estimate:
Attach additional documentation such as previous pricing, documentation, emails, internet screen shots, estimates on letterhead, etc.
Published Price List (attach source and date)
_X_ Historical Pricing (attach copy of documentation from previous PO/Contract)
Comparable Purchases by Other Agencies (attach email correspondence)
Engineering or Technical Estimate (attach) Independent Third-Party Estimate (attach)
Other (specify) attach documentation
Pre-established pricing resulting from competition (Contract Modification only)
Through the method(s) stated above, it has been determined the estimated
total cost of the goods/services is \$ \$150,000 Per Year_
The preceding independent cost estimate was prepared by:
Name
Raymundo Delgadillo
Signature



# Scope of work for Cummins, Allison, and Thermoking Engine Diagnostics and repair

NORTA Bus maintenance needs diagnostic services from an authorized Cummins, Allison, & Thermoking. We are looking for on-site diagnostic services and minor repairs, and when needed we could send the vehicle to a local shop or they can do it in our shop. We need 590 hours of labor for a cost 220 per hour including traveling cost. At total cost of \$ 130,000 and an estimated miscellaneous expense of \$20,000 for a total budget of \$150,000.

Thanks,

Raymundo Delgadillo

Director of Bus Maintenance
504-827-8400

Rmoser@rtaforward.org

# TECHNICAL SPECIFICATIONS FOR BUS DIAGNOSTIC AND REPAIRS

#### 1. SCOPE

The RTA requires vehicle diagnostic and repair services for their bus fleet. This service is on an as-needed basis; this includes but is not limited to the following vehicle systems; engines, transmissions, A/C HVAC.

Multiple vendors may be selected if needed to complete the needs of the agency. The term of this agreement would be two years, with a one-year option to renew.

The contractor must be an authorized Cummins, Thermo King, or Allison dealer.

#### 2. APPLICATION AND SIZE

Vehicles include 2008-2012 Orion VII buses (35ft and 40ft buses). New Flyer 60ft Articulated buses. 2019-2021 New Flyer Xcelcior (35 and 40ft buses).

All units are equipped with Allison Transmissions, Thermo King A/C units, and Cummins ISL engines.

#### 3. PERFORMANCE

The specified component shall perform to all Cummins, Tristate, Or Allison OEM standards and specifications upon completion of diagnostics or repairs.

#### 4. QUALITY

#### Repairs

Only the original manufacturer's parts (OEM) will be allowed. No substitutions or modifications will be allowed or accepted.

OEM engine components parts that have been modified or misapplied, according to the OEM engine supplier's original design and intention, will not be allowed or accepted.

#### 5. DOCUMENTATION

All bidders shall furnish the Regional Transit Authority with their bid, complete with descriptive literature covering and identifying the items to be supplied, including specification sheets and performance data.

Failure to submit the required information and to complete attachment incorrectly shall render a bid non-responsive and shall cause its rejection.

#### 7. DELIVERIES

The contractor must be able to supply on sight support service and diagnostics within 24 hours of being notified of needed services.

RTA agrees to deliver and pick up buses from the Contractor place of business located within fifty (50) miles of the RTA's garage if on sight repairs are not possible.

#### 8. REPAIR

The contractor agrees to complete repairs in a first-class manner within ten (10) business days from delivery.

If a project takes longer than 10 days due to unforeseeable circumstances, RTA must be notified immediately and negotiate a new and acceptable timeline in good faith;.

If the RTA is not notified, the contractor agrees to pay \$100 for each day after the ten days the vehicle is not available.

#### 9. PRICING

The price for the supplied specified item shall be a fixed labor rate for the length of the contract period.

Engine hourly labor rate total:	
Transmission hourly labor rate total:	
A/C, HVAC hourly labor rate total:	
Fees:	
On Sight Service call charge:	
Shop Supply fee:	
Additional Fees:	



### Kenworth of Louisiana - Harahan

1001 Edwards Ave Harahan, Louisiana 70123 Phone: (504) 818-0100 PACCAR SOLUTIONS

Case Number: 9099724 - Repair Order Number: 11450 Purchase Order Number: n/a

Service Writer: Lovell, Rob - Case Date: 08/04/21 11:12 am CDT

Regiona	l Transit Auth	Unit #: 209			
Address	: ATTN:CARMEN CAMPBELL	Asset:	2010 ORION BUS ORION VII [ URBAN 40 ]	Miles 500,611	
	2817 CANAL BLVD	Serial #:	A6706507		回数编回
	NEW ORLEANS, LA 70119	VIN:	1VHFH3G23A6706507		754 MARCO
Phone:	000000000	Engine:	Not Supported		37. Alle
Fax:	(504) 648-5239	Engine Hou			回路公司
Cust #:	06109	3			A6706507

#### Complaint:

C/S unit is popping back through the intake. Check and advise.

Operation	Operation	Labor	Parts	Core Charge	Total
1	SANITATION PROCESS	\$0.00	\$0.00	\$0.00	\$0.00
2	TRIAGE - DOWNLOAD FAULT CODES CHECK FOR CAMPAIGNS TRIAGETRIAGE	\$36.90	\$0.00	\$0.00	\$36.90
	Complaint: C/S unit is popping back through the intake. Check and advise.				
3	DIAGNOSE DIAGNOSE099-107-000	\$258.30	\$0.00	\$0.00	\$258.30
	Complaint: Diagnostic/troubleshooting time for engine related complaints				
	Cause: Installed driveshaft. Batteries dead, will not start. Jump started. Ran engine and inspected. Verified engine popping through intake. Removed crossover tube and valve cover. Found #6 exhaust push tube out of line with the exhaust rocker. The top of the push tube was damage and the push tube was bent. Replaced push tube with one on hand.				
	Correction: Need to run overhead & run unit at idle to see if popping still occurs.				
4	CYLINDER HEAD 040045-007-000	\$0.00	\$0.00	\$0.00	\$500.00
	Complaint: Run overhead/check & set valve lash				
	Cause: Ran the overhead adjustment. All overhead components appeared to be ok. Overhead was slightly out of adjustment.				
	Correction: Installed the valve cover and the crossover tube.				
5	ROAD TEST - VERIFY REPAIR VERIFICATIROAD TEST	\$184.50	\$0.00	\$0.00	\$184.50
	Complaint: Regen & road test to verify repairs				

Dealer: Kenworth of Louisiana - Harahan - Version: 1 - Posted: 08/06/21 09:52 am CDT - Fleet: Regional Transit Auth - Unit: 209 - Asset: 2010 ORION BUS ORION VII [ URBAN 40 ] - S/N: A6706507

Notes: [8/4/2021 at 11:14 am CDT] - Unit was checked in at Kenworth of Louisiana -Parts: \$0.00 Harahan, arrival time: . Labor: \$479.70 Repair status set to Checked-in. Core: \$0.00 [8/6/2021 at 09:52 am CDT] - Approval Requested for the estimate version 1. Haz. Waste: \$14.39 total \$1,131.36. View the estimate. NOTE: Please review the attached estimate. Shop: \$43.17 Let us know if you have any questions. Reply to this case or call us directly with Freight: approval. Thank you! \$0.00 Repair status set to Hold (auth). Tax: \$94.10

TOTAL: \$1,131.36

NOTICE: The undersigned being the owner or authorized agent for the owner of the above described vehicle, part, or equipment does hereby authorize Kenworth of South Louisiana and its agents, herein after, The Dealer, to perform the above described work and furnish the necessary material on said vehicle part and/or equipment and does herby authorize The Dealer and its agents to operate said vehicle and/or equipment on the streets, highways, or elsewhere as needed to correct complaints described above. The customer is responsible for payment of and for all work performed. Failure to provide payment immediately upon completion of repairs shall result in charges equal to legal interest starting on the date of arrival to The Dealer. In addition to any interest for unpaid repairs, The Dealer shall be entitled to attorney's fees, costs, and expenses. The dealer is not responsible for any valuables left in the vehicle and shall be held harmless for any and all property. The dealer is not responsible for any trailers whatsoever even if left on premises. The shop rate is \$140.00 per hour; minimum two hours on all diagnostic work.

ATTENTION CUSTOMERS: Please be aware that if it is determined that in the process of repairing your vehicle your vehicle has been modified from original equipment as approved by its EPA certification Kenworth of Louisiana is required to assemble your unit back into compliance. At this time you will be provided with an estimate to bring the unit into compliance. If you choose not to bring your vehicle into compliance, all additional work on your vehicle will cease and you will be required to pay any and all associated costs for work performed to your vehicle up to that point, even if the repair is incomplete. Failure to accept this estimate of repairs will release Kenworth of Louisiana from any and all liability for workmanship or additional costs and expenses due to the illegal emissions modifications to your vehicle. We are also required by law to report these modifications to the truck OEM and engine manufacturer, both of which will void your warranty and those parties may choose to report the modifications to the EPA.



#### Kenworth of Louisiana - Harahan

1001 Edwards Ave Harahan, Louisiana 70123

Phone: (504) 818-0100

Case Number: 9058221 - Repair Order Number: 11396

Purchase Order Number: n/a

Service Writer: Stokes, Justin - Case Date: 07/28/21 01:55 pm CDT



Regiona	l Transit Auth	Unit #: <b>7063</b>	81 194		
Address	: ATTN:CARMEN CAMPBELL	Asset:	2010 ORION BUS	Miles 189,565	回数编画
	2817 CANAL BLVD	Serial #:	A6706381		
	NEW ORLEANS, LA 70119	VIN:	1VHFH3G27A6706381		AL AND
Phone:	000000000	Engine:	ISL		
Fax:	(504) 648-5239	Engine Hou	ırs: 2743		A6706381
Cust #:	06109				

#### Complaint:

C/R please inspect and advise the following concerns. 1. Head gasket is leaking.

Operation	Operation	Labor	Parts	Core Charge	Total
1	SANITATION PROCESS	\$0.00	\$0.00	\$0.00	\$0.00
2	TRIAGE - DOWNLOAD FAULT CODES CHECK FOR CAMPAIGNS TRIAGETRIAGE	\$36.90	\$0.00	\$0.00	\$36.90
	Complaint:  C/R please inspect and advise the following concerns. 1. Head gasket is leaking.				
3	DIAGNOSE DIAGNOSE099-107-000  Complaint: Diagnostic/troubleshooting time for head gasket leak	\$258.30	\$0.00	\$0.00	\$258.30
4	CYLINDER HEAD 040045-007-000  Parts: (1.0) ELEMENT-CRANKCASE VENTILATIO, (1.0) FILTER-LUBE, (1.0) GASKET,CYLINDER HEAD, (1.0) KIT, (6.0) CLEANER -NON-CHLORINATED BRK HIGH V.O, (6.0) ROTELLA 15W40 CJ4 GALLON	\$4,489.50	\$353.56	\$0.00	\$4,843.06
	Complaint: Replace head gasket set				

Notes: [7/28/2021 at 02:06 pm CDT] - Unit was checked in at Kenworth of Louisiana -

Harahan, arrival time: .

Repair status set to Checked-in.

[7/29/2021 at 11:59 am CDT] - Good evening Team. We are currently waiting

on a tech to become available to proceed with repairs.

[8/3/2021 at 12:15 pm CDT] - Approval Requested for the estimate version 1, total \$5,908.98. View the estimate. NOTE: Please review the attached estimate to replace head gasket.. Let us know if you have any questions. Reply to this

case or call us directly with approval. Thank you!

Repair status set to Hold (auth).

Parts: \$353.56 Labor: \$4.784.70

Core: \$0.00

Haz. Waste: \$25.00

Shop: \$250.00

Freight: \$0.00

> Tax: \$495.72

TOTAL: \$5,908.98

NOTICE: The undersigned being the owner or authorized agent for the owner of the above described vehicle, part, or equipment does hereby authorize Kenworth of South Louisiana and its agents, herein after, The Dealer, to perform the above described work and furnish the necessary material on said vehicle part and/or equipment and does herby authorize The Dealer and its agents to operate said vehicle and/or equipment on the streets, highways, or elsewhere as needed to correct complaints described above. The customer is responsible for payment of and for all work performed. Failure to provide payment immediately upon completion of repairs shall result in charges equal to legal interest starting on the date of arrival to The Dealer. In addition to any interest for unpaid repairs, The Dealer shall be entitled to attorney's fees, costs, and expenses. The dealer is not responsible for any valuables left in the



# Tri State Refrigeration, Inc.

334 Butterworth Street - Jefferson, LA 70121 Phone: (504) 733-9581 - Fax: (504) 733-4631 www.tsrtk.com

Remit To:

7387 E. Industrial Ave. Baton Rouge, LA 70805

**NET 30 DAYS** 

SOLD TO S0423

RTA COST CENTER#460 2817 CANAL STREET NEW ORLEANS, LA 70119

SHIP TO TRI STATE REFRIGERATION INC.

334 BUTTERWORTH ST.

JEFFERSON, LA 70121

INVOICE#

HR 1944.0 W:00 ATHENIA SN: 3000153298 Date 7/22/21 WORK ORDER 13:41:04 PRT: Sold By: 25 PO #: 913319 WS41913 Tax #: Ship By:

Qty Description Price Amount Customer Unit: 274 COMPLAINT: CHECK AND ADVISE Group: 01 CORRECTION: 06/01/2021-CUSTOMER CAME INTO SHOP. INSPECTED OVER AND FOUND CONDENSER LEAKING AND BOTH BAD EXPANSION VALVES. MADE UP QUOTE FOR REPAIRS AND SENT TO CUSTOMER FOR APPROVAL. GOT APPROVAL AND ORDERED PARTS.
07/21/2021-REPAIR AS PER QS03879. R/R CURBSIDE
CONDENSER AND BOTH EXPANSION VALVES. R/R DRIER. LEAR
CHECKED SYSTEM WITH NITROGEN. EVACUATED AND CHARGED
SYSTEM. RAN AND CHECKED OPERATIONS. LABOR A/C \*\* TOTAL LABOR A/C 1374.11 PARTS SHOP 67-2503 306-221 2030743 61-5328 880007 562-010 3094.71 70.09 450.00 473.26 9.50 47.00 3094.71 70.09 18.00 236.63 COIL ASSY C DRIER FILTE FREON, R407C 00000 TK TK 00000 J - 6 - 800000 CG VALVE, EX NITROGEN EXP H 5-0TK JS 00000 9.50 00000 47.00 ROD, BLUE-45 INSUL T M 3-4
\*\* TOTAL PARTS SHOP 8990 . 48 00000 4 MEI A/C 4146.48 SHOP SUPPLIES 00000 SUPPLIES 50.00 FEES ENVIRO 1 ENVIRONMENTAL FEES 21.50 21.50

\*CORES MUST BE RETURNED WITHIN 30 DAYS TO RECEIVE CREDIT\*

\*\* SUBTOTAL

5592.09

Phone: (504)827-8478

PAY THIS **AMOUNT** 

\$5592.09

Charge Sale

#### ACCOUNTS RECEIVABLE

P.O. Box 377 Brandon, FL 33509-0377 (813) 540 1919 ar@rtsallison.com



#### NEW ORLEANS BRANCH

129 Industrial Drive Slidell, LA (985) 200-0400 www.rtsallison.com

# RELIABLE TRANSMISSION SERVICE, INC. BECAUSE ALLISON IS ALL WE DO!

\*\*\* Customer Review \*\*\*

Date / Time: 7/15/2021 8:18:56AM

Repair Order: 107

Customer: 12047

Branch: SLA Invoice Total: \$ 8,824.00

\*\*\*Charge\*\*\*
Page 1 of 3

Bill To: NEW ORLEANS REGIONAL TRANSIT AUTHORITY

2817 CANAL ST.

NEW ORLEANS, LA 70119

Shop: 504-827-8400

Fax:

504-648-5080

Ship To: NEW ORLEANS REGIONAL TRANSIT AUTHO

2817 CANAL ST.

NEW ORLEANS, LA 70119

Customer P/O: REQUIRED

nschmitt

Completion Date:

Unit Number: 266

Model Year: 2022

Make/Model: Van Hool Bus C2405

Type: Tour Bus VIN: 1VHFH3G23A6706877

Task: 1

SC

Service Call

Department: Field Svc

Supp. Part	Description / Ref Number	U/M Quantity	Extended Price Price
Labor Quote: 222.00			
		Task Subtotals	
		Parts:	\$0.00
		Core Chg:	\$0.00
		Core Ret:	\$0.00
		EHC:	\$0.00
		Labor:	\$222.00
		Miscellaneous:	\$0.00
		Task 1 Subtotals:	\$222.00

Task: 2 R&R

Complaint:

Remove Or Replace Trans

CUSTOMER REQUESTS AN EXCHANGE TRANSMISSION WITH LABOR

Department: Field Svc

Supp. Part	Description / Ref Number		U/M	Quantity	Price	Extended Price
E017124	Transmission	Part	EA	1.00	4,825.00	4,825.00
Stocking Number:	Serial Number:					NW.55250555
E017124-C	Transmission -Core	Inherent		1.00	1,600.00	1,600.00
Labor Quote: 1,600.00					•	,
		Tas	k Subtot	als		
				Parts:	\$4	1,825.00
				Core Chg:	\$1	,600.00
				Core Ret:		\$0.00
				EHC:		\$0.00
				Labor:	\$1	,600.00
				Miscellaneous:		\$0.00
			T	ask 2 Subtotals:	\$8	3,025.00

Task: 3 SR

Complaint:

Service Or Repair Of Trans

REMOVE FAILED UNIT AND TAKE BACK TO OUR SHOP AND CHECK COOLER.

Department: Field Svc

Supp. Part Description / Ref Number U/M Quantity Price Price

#### ACCOUNTS RECEIVABLE

P.O. Box 377 Brandon, FL 33509-0377 (813) 540 1919 ar@rtsallison.com



#### NEW ORLEANS BRANCH

129 Industrial Drive Slidell, LA (985) 200-0400 www.rtsallison.com

#### RELIABLE TRANSMISSION SERVICE, INC BECAUSE ALLISON IS ALL WE DO!"

\*\*\* Customer Review \*\*\*

Date / Time: 7/15/2021 8:18:56AM

Repair Order: 107 Customer: 12047 Branch: SLA

Invoice Total: \$8,824.00

\*\*\*Charge\*\*\*
Page 2 of 3

Bill To: NEW ORLEANS REGIONAL TRANSIT AUTHORITY

2817 CANAL ST.

NEW ORLEANS, LA 70119

Shop: 504-827-8400

Fax: 504-648-5080

Ship To: NEW ORLEANS REGIONAL TRANSIT AUTHO

2817 CANAL ST.

NEW ORLEANS, LA 70119

Customer P/O: REQUIRED nschmitt	Completion Date	
Labor Quote: 280.00		
	Task Subtotals	
	Parts:	\$0.00
	Core Chg:	\$0.00
	Core Ret:	\$0.00
	EHC:	\$0.00
	Labor:	\$280.00
	Miscellaneous:	\$0.00
	Task 3 Subtotals:	\$280.00

Task: 4 SC

Complaint:

Service Call

TRAVEL BACK TO CUSTOMERS LOCATION AND INSTALL NEXT DAY.

Department: Field Svc

upp. Part	Description / Ref Number	U/M Quantity	Price	Extended Price
Labor Quote: 222.00				
		Task Subtotals		
		Parts:		\$0.00
		Core Chg:		\$0.00
		Core Ret:		\$0.00
		EHC:		\$0.00
		Labor:	:	\$222.00
		Miscellaneous:		\$0.00
		Task 4 Subtotals:		\$222.00

#### ACCOUNTS RECEIVABLE

PO, Box 377 Brandon, FL 33509-0377 (813) 540 1919 ar@rtsallison.com



#### NEW ORLEANS BRANCH

129 Industrial Drive Slidell, LA (985) 200-0400 www.rtsallison.com

## RELIABLE TRANSMISSION SERVICE, INC. BECAUSE ALLISON IS ALL WE DO!"

\*\*\* Customer Review \*\*\*

Date / Time: 7/15/2021 8:18:56AM

Repair Order: 107 Customer: 12047 Branch: SLA

Invoice Total: \$8,824.00

\*\*\*Charge\*\*\* Page 3 of 3

Bill To: NEW ORLEANS REGIONAL TRANSIT AUTHORITY

2817 CANAL ST.

NEW ORLEANS, LA 70119

Shop: 504-827-8400

504-648-5080

Ship To: NEW ORLEANS REGIONAL TRANSIT AUTHO

2817 CANAL ST.

NEW ORLEANS, LA 70119

Customer P/O: REQUIRED

nschmitt

Completion Date:

Customer Tax ID:

iotais
--------

**Total Parts:** \$4,825.00 **Total Core Chg:** \$1,600.00 **Total Core Ret:** \$0.00 **Total EHC:** \$0.00 **Total Labor:** \$2,324.00 Total Miscellaneous: \$0.00 **Total Shop Supplies:** \$75.00 Invoice Subtotal: \$8,824.00 **Total Tax:** 

\$0.00

Invoiced Total:

\$8,824.00

#### Payment Method

Charge